

# General Environmental Incident Summary

**Incident:** 5211      **Date/Time Notice:** 8/29/2016      16:43      **DEM Incident No:**

**Responsible Party:** Ferus Natural Gas (CNG) LLC

**Date Incident:** 8/26/2016      **Time Incident:** 02:30      **Duration:**

**County:** Mountrail      **Twp:** 156      **Rng:** 93      **Sec:** 30      **Qtr:**

**Lat:** 48.29950      **Long:** -102.68240      **Method:** Interpolation from map

**Location Description:** 1/2 mile past mile marker 77 east on Hwy 2 turn south on 94th ave . Go south to 61 st turn west 1.5 miles into location ( keep right into "Y")

**Submitted By:** Cam Jesse

**Affiliation:** Director, HSE Ferus

**Address:** Suite 1220

401 9th Ave SW

**City:** Calgary

**State:** AB

**Zip:** T2P3C5

## Received By:

**Contact Person:** Darwin Fuller  
5812 Jefferson Lane  
Williston, ND 58801

**Distance Nearest Occupied Building:** 0.75 Miles

**Release Contained:** No

**Type of Incident:** Burst disk activation

**Description of Released Contaminant:** Natural Gas

**Volume Spilled:** 8741.00 pounds

**Ag Related:** No

**EPA Extremely Hazardous Substance:** No

**Reported to NRC:** No

## Cause of Incident:

Loading operator entered incorrect volume to load trailer and overloaded causing burst disk to open. once burst disk opened load escaped to atmosphere.

## Risk Evaluation:

High pressure venting, potential for flammable atmosphere,

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 01 - air

## Potential Environmental Impacts:

Minimal GHG effect

## Action Taken or Planned:

Looking into automating PLC at loading station to ensure that overload risk is reduced.

**Wastes Disposal Location:** N/A

## Agencies Involved:

## ***Updates***

---

***Date:*** 8/29/2016    ***Status:*** Reviewed - Assigned to NDDoH Division

***Author:*** Souder, Taylor

***Updated Volume:***

***Notes:***

Report forwarded to Air Quality Division within the NDDoH.